



1

Description:

Entry monument



Photo Number

2

Description:

Possible gap/moisture entry on monument





3

Description:

View from entry



Photo Number

4

Description:

View from entry





5

Description:

Swimming pool and deck



Photo Number

6

<u>Description</u>:

Pool equipment





7

Description:

Corrosion on panel in pool room.



Photo Number

8

Description:

Clubhouse water heater





9

Description:

Clubhouse washing machines



Photo Number

10

Description:

Clubhouse dryers





11

Description:

Clubhouse hallway and mailboxes.



Photo Number

12

Description:

Clubhouse bathroom





<u>Description</u>: Townhouse front



Photo Number

14

Description:

Townhouse rear





Description:

Wood/lattice fence and light pole



Photo Number

16

Description:

Townhouse, sidewalk, and fence






<u>Description</u>: Corrosion at handrail base



Photo Number 18

<u>Description</u>: Damaged ventilation screen





Description:

Clubhouse unprotected beam ends



Photo Number **20**

Description:

Steps with missing handrail





<u>Description</u>: Steps with missing handrail



Photo Number **22**

Description:

Aging wood shingles on carport





<u>Description</u>: Carport and driveway



Photo Number **24**

<u>Description</u>: Emergency exit gate





<u>Description</u>: Carport structure



Photo Number **26**

<u>Description</u>:

Dumpster enclosure





<u>Description</u>: West building and entry



Photo Number **28**

<u>Description</u>: Deteriorating steps





<u>Description</u>: Step bracket corrosion



Photo Number **30**

<u>Description</u>: West sun deck





<u>Description</u>: Center building entry



Photo Number 32

<u>Description</u>: East sun deck





<u>Description</u>: Center building



Photo Number

34

Description:

Rear of east building





<u>Description</u>:

East sun deck structure



Photo Number

36

Description:

Rear of center building. Note weathering deck rim joists.





<u>Description</u>: Rear of buildings



Photo Number **38**

<u>Description</u>: Townhouse roof





<u>Description</u>: Cracking at townhouse storage roof



Photo Number **40**

<u>Description</u>: Carport roof-note newer parapet section at right





<u>Description</u>: Carport roof deterioration



Photo Number **42**

<u>Description</u>: Carport roof cracking